

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director OLENE S. WALKER
Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection:					
OGM	Steve Demczak Environmental Scientist III				
Company	Dennis Oakley Environmental Engineer				

Inspection Report

Permit Number:	C0150018			
Inspection Type:	COMPLETE			
Inspection Date:	Tuesday, August 24, 2004			
Start Date/Time:	8/24/2004 10:00:00 AM			
End Date/Time:	8/24/2004 2:00:00 PM			
Last Inspection:	Monday, July 26, 2004			

Inspector: Steve Demczak, Environmental Scientist III

Weather: Warm, 70's, Cloudy
InspectionID Report Number: 378

Accepted by: pgrubaug

9/28/2004

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: DEER CREEK MINE

Address: PO BOX 310, HUNTINGTON UT 84528

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages

Total Permitted	22,769.06	
Total Disturbed	84.34	
Phase I		
Phase II		
Phase III		

Mineral Ownership Federal

State

Types of Operations

✓ Underground

☐ Surface

 □ County
 □ Loadout

 ✔ Fee
 □ Processing

 □ Other
 □ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Conditions:

- 1) During entry development if sustained quantities of groundwater are encountered which are greater than 5 gpm from a single source in an individual entry, and which continue after operational activities progress beyond the area of groundwater production, PacifiCorp must monitor these flows and notify the Division within 24 hours prior to initiation of monitoring.
- 2) Vehicle access will not be allowed in Rilda Canyon from December 1 to April 15 for construction and/or maintenance of the Rilda Canyon Surface Facilities without prior written approval from the Division. This condition is for normal working circumstances and does not apply in an emergency situation.
- 3) PacifiCorp will submit water quality data for the Deer Creek Mine in an electronic format through the EDI web site.
- 4) The permittee is meeting these conditions at this time.

Permitting Actions - No pending permit actions at this time.

Violations: None.

Inspector's Signature

Date

Wednesday, August 25, 2004

Increase ID North and 20

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 www.ogm.utah.gov



Permit Number: C0150018
Inspection Type: COMPLETE

Inspection Date: Tuesday, August 24, 2004

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓			
2,	Signs and Markers	V			
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions	✓		✓	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	~		~	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives	V			
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments	~		~	
8.	Noncoal Waste	~		~	
9.	Protection of Fish, Wildlife and Related Environmental Issues	V			
10.	Slides and Other Damage	~			
11.	Contemporaneous Reclamation	✓			
12.	Backfilling And Grading	~			
13.	Revegetation	✓			
14.	Subsidence Control	~			
15.	Cessation of Operations	✓			
16.a	Roads: Construction, Maintenance, Surfacing	✓			
16.b	Roads: Drainage Controls	✓			
17.	Other Transportation Facilities	✓			
18.	Support Facilities, Utility Installations	✓		V	
19.	AVS Check	✓		✓	
20.	Air Quality Permit	~		~	
21.	Bonding and Insurance	~		✓	
22.	Other	Y		V	

Permit Number: C0150018 Inspection Type: COMPLETE

Inspection Date: Tuesday, August 24, 2004

Page 3 of 4

3. Topsoil

I inspected the waste rock topsoil pile. The area had several rain storms in the past two weeks. The silt fences around the pile were performing as designed. There were no signs of wind or water erosion. The pile does have some vegetation cover helping to prevent erosion to the pile.

4.a Hydrologic Balance: Diversions

The diversions were spot-checked and were functioning as designed. Several diversions and dugout ponds were recently cleaned out.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The permittee has conducted second quarter sediment pond inspections. No hazardous conditions were noted in the report. I inspected the sediment ponds and found no hazardous conditions existing with the ponds during the inspection.

4.c Hydrologic Balance: Other Sediment Control Measures

Several sediment traps have been cleaned out since the last inspection. Due to several rain storms, sediment had gathered within the sediment traps.

4.d Hydrologic Balance: Water Monitoring

The permittee has submitted to the Division the second quarter water monitoring information into the EDS. The permittee is currently taking water samples for the third quarter.

4.e Hydrologic Balance: Effluent Limitations

The UPDES reports were inspected and the permittee had met the requirements of the permit.

7. Coal Mine Waste, Refuse Piles, Impoundments

The second quarter refuse pile inspection report was conducted by the permittee. No hazardous conditions were documented. I inspected the refuse pile and found no hazardous conditions.

8. Noncoal Waste

The mine site was clear of non-coal waste material.

18. Support Facilities, Utility Installations

No new construction has taken place since the last inspection.

19. AVS Check

The permittee has submitted and received approval from the Division for updating the AVS information.

Inspection Continuation Sheet

Permit Number: C0150018
Inspection Type: COMPLETE

Inspection Date: Tuesday, August 24, 2004

Page 4 of 4

20. Air Quality Permit

21. Bonding and Insurance

The insurance accord form was inspected. The form complied with the R645 Coal Rules. The insurance will expire on 04/01/2005. The insurance company is Assoc. Electric & Gas INS SVCS LTD.

22. Other

The SPCC Plan was inspected. The plan was updated on February 27, 2004. This document is P.E. certified.